

TO BE FILLED BY THE INSPECTING OFFICER
(Assistant Engineer, LID&EW Section, Kongad Grama panchayath)

No. FC-13/2025-26 dated 16.09.2025

Name of School

KEM SECONDARY SCHOOL, KONGAD

- | | | |
|--|---|---|
| 1. Name of Officer | : | Bincy Thankachan, Assistant Engineer |
| 2. Location | : | Kongad |
| 3. Period which the certificate is issued | : | 2025-26 |
| 4. Type of Building | : | RCC Building GF & FF |
| | | <u>Main Block</u> |
| | | GF - 6.0*6.0*3.6 (9 Class room RCC) |
| | | FF - 6.0*6.0*3.6 (1 Class room GI) |
| | | FF - 6.0*6.0*3.6 (9 Class room GI) |
| | | <u>HS Block</u> |
| | | GF - 6.10*6.10*3.6 (3 Class room RCC) |
| | | FF - 6.10*6.10*3.6 (3 Class room RCC) |
| 5. Nature of defect if any | : | |
| a) Foundation and Basement | : | |
| b) Super Structure | : | |
| c) Doors and Windows | : | |
| d) Wood work Wrought & put up | : | |
| e) Roof | : | |
| f) Flooring | : | |
| g) Miscellaneous | : | |
| 6. Any Major defects noticed which will render the building unsafe in any manner | : | No |
| 7. Whether maintenance work have been done | : | Yes |
| 8. Weather the structure is sound for conducting classes | : | Structure is sound for conducting classes under normal weather condition. |


Note: All toilets should be finished with ceramic tiling to ensure hygiene.


HS block – Second Floor class room should be provided with extra false ceiling.

Certified that, the school was inspected by me on 16.09.2025, and found fit to conduct classes for the period 2025-26 for the reasons stated above.

Place: Kongad

Date: 16.09.2025




Signature
BINCY THANKACHAN
PEN: 800467
Assistant Engineer
LSGD Section (LID & EW)
Kongad Grama Panchayath